## Oil Field Environmental Incident Summary

**Responsible Party:** SECURE ENERGY SERVICES USA, LLC **Well Operator:** SECURE ENERGY SERVICES USA, LLC

Well Name: 13 MILE SWD 1

Field Name: TYRONE Well File #: 90159

Date Incident:3/20/2016Time Incident:01:00Facility ID Number:County:WILLIAMSTwp:156Rng:101Sec:12Qtr:Location Description:Unintended release contained by gutters and sumps within building

Submitted By: John Albert Received By:

Contact Person: Josh Mosbrucker

555 17TH ST STE 800 DENVER. CO 80202-3908

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 1500 Feet **Distance Nearest Water Well:** 200 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 70 Barrels 70 Barrels

**Description of Other Released Contaminant:** 

Process tank clarified water and sediment (~2% by volume)

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

All released fluid contained within building gutters and sumps

Areal Extent:

## Potential Environmental Impacts:

Negligible. All spilled materials were contained within building and managed by sumps. Minimal sedimentary material in gutters shows no excess norm impact.

## Action Taken or Planned:

Spilled material rinsed to sumps and recaptured. Affected areas surveyed for potential norm contamination, (none.) Check valve in question will be examined and replaced if needed. Operator at fault will recieve written warning and be retrained to manually isolate tanks after each transfer. Other operators will be instructed to be more attentive to alarms.

Wastes Disposal Location: Spilled materials are recaptured and will be processed on site.

Agencies Involved:

## **Updates**

Date: 3/22/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the release remained on location. NDIC has oversight.